
MIC-009269 OK	9-NORMAL, NB, 109269, SF031 12	917 320250613 0054	ULC U W OK CERTCERTCERT TRD RAMPBUM	
	HICLE DESCRIPTION RANGER 2025 SUPERCREW 4X4 XL 128" WHEELBASE 2.3L ECOBOOST ENGINE 10-SPEED AUTO TRANSMISSIC	EXTERIOR OXFORD WI INTERIOR EBONY CLC		Fuel Economy MPG Standard 87 MPG.
STANDARD EQUIPMENT INCLUDED EXTERIOR • DAYTIME RUNNING LAMPS • EASY FUEL® CAPLESS FILLER • FENDER BADGE • FULL SIZE SPARE TIRE/WHEEL • FULLY BOXED STEEL FRAME • GRILLE - BLACK • HEADLAMPS - AUTO ON/OFF • PICKUP BOX TIE DOWN HOOKS • REMOTE TAILGATE LOCK • WHEEL LIP MOLDINGS • WIPERS- INTERMITTENT INCLUDED ON THIS VEHICLE EQUIPMENT GROUP 100A • XL SERIES OPTIONAL EQUIPMENT/OTHER LT255/70R 17 A/T OWL TIRE STX APPEARANCE PACKAGE .FOG LAMPS .17" SILVER PAINTED ALUM WHL FRONT LICENSE PLATE BRACKET 120V/400W IN-CAB & IN-BED PWR		FUNCTIONAL • AUDIO - 6 SPEAKERS • BRAKES - ANTI-LOCK SYSTEM • ELECTRIC PARKING BRAKE • INDEPENDENT FRONT SUSPEN • PRE-COLLISION ASSIST W/AEB • REAR VIEW CAMERA • REMOTE KEYLESS ENTRY • SELECTSHIFT® • SYNC®4A PRICE IN BASE PRIC TOTAL VEN	SAFETY/SECURITY • AIRBAGS - SAFETY CANOPY® • BELT-MINDER CHIME • CTR HIGH MOUNT STOP LAME • LATCH CHILD SAFETY SYSTEM • PASSIVE ANTI-THEFT SYSTEM • TIRE PRESSURE MONIT SYS WARRANTY • 3YR/36,000 BUMPER / BUMPE • 5YR/60,000 POWERTRAIN • 5YR/60,000 ROADSIDE ASSIST (M CORMATION *E \$36,7 TIONS/OTHER \$36,7 ************************************	MPGe. MPG. MPG
		GG		Frontal CrashDriver PassengerBased on the risk of injury in a frontal impact. Should ONLY be compared to other vehicles of similar sizeSide CrashFront seat Rear seatBased on the risk of injury in a side impact.Based on the risk of injury in a side impact.RolloverBased on the risk of rollover in a single-vehicle crash.Star ratings range from 1 to 5 stars (*****), Source: National Highway Traffic Safety Adm www.safercar.gov or 1-888-327
	RP28	RAIL Scan	L MSRP \$38,820.0 The QR Code to	
	ITEM #:	get m	ore details about 🛛 🎆	WARNING: Operating, servicing and maintaining a p vehicle can expose you to chemicals including engine lead, which are known to the State of California to cause ca



##