FD

| Go Further 5  | 50<br>19 F-150 4X2 SUPER<br>5" WHEELBASE<br>0L V8<br>.EC 10-SPEED AUTO | INT  | KF<br>INGOT SILVER<br>ERIOR<br>MEDIUM GRAY CLOTH 44   | <b>B18817</b><br>0/20/40  | EPA<br>DOT Fuel Economy and Env<br>Fuel Economy<br>MPG Value<br>do not reflet<br>based on E   |
|---|--|--|---|---|---|
| EXTERIOR   INTER     • DAYTIME RUNNING LIGHTS   • 1170     • EASY FUEL® CAPLESS FILLER   • 60/4     • FOG LAMPS   SEA     • FULLY BOXED STEEL FRAME   • A/C     • HALOGEN HEADLAMPS   • CRU     • HEADLAMPS - AUTO HIGH BEAM   • CRU     • HEADLAMPS - AUTO LAMP   • DOD     (ON/OFF)   • DOW     • LOCKING REMOVABLE TAILGATE   • ILLU     • MANUAL FOLD POWER MIRRORS   • OUT     • PICKUP BOX TIE DOWN HOOKS   • POW     • PICKUP BOX TIE DOWN HOOKS   • POW     • REAR PRIVACY GLASS   • TILT     • TRAILER SWAY CONTROL   • TILT     INCLUDED ON THIS VEHICLE   (M     EQUIPMENT GROUP 300A   • XLT SERIES     OPTIONAL EQUIPMENT/OTHER   .17" SILVER PAINTED ALUMINUM | SRP)   | AUTO START STOP CURVE CONTROL DYNAMIC HITCH AS ELECTRIC-ASSIST I FAIL-SAFE COOLINI FORDPASS <sup>TM</sup> COI HOTSPOT TELEMAT GAS-CHARGED SHO MYKEY® OUTBOARD MNTD                                     | AKES W/ABS<br>TECH<br>SSIST<br>PARK BRAKE<br>G SYSTEM<br>NNECT 4GWI-FI<br>TICS MODEM<br>OCKS<br>REAR SHOCKS<br>SIST W/AEB<br>A<br>AURBAC<br>• AIRBAC<br>• AIRBAC<br>• CTR HI<br>• PERIMI<br>• SECUR<br>• SOS PC<br>• SOS PC<br>• SOS PC<br>• SYR/60<br>• SYR/60 | ,000 BUMPER / BUMPER<br>,000 POWERTRAIN<br>,000 ROADSIDE ASSIST<br>(MSRP)<br>\$39,420.00<br>1,995.00<br>S/OTHER 41,415.00 | Image: Start Star |
|   | RAMP ONE   |  | TOTAL MSRP  | \$42,910.00   | 1FTEW1C5XKFB18817   |
|   | Information Disclosure<br>State and Local taxes                        | CONVOY<br>ITEM #:<br>72-B31M O/T 9Z<br>ursuant to the Federal Automobile<br>e Act. Gasoline, License, and Title Fees,<br>are not included. Dealer installed<br>s are not included unless listed above. | FORD CREDIT   | L ORDER   | WARNING: Operating, servicing and maintaining a pass<br>vehicle can expose you to chemicals including engine ex<br>lead, which are known to the State of California to cause cance<br>To minimize exposure, avoid breathing exhaust, do not idle the<br>vehicle in a well-ventilated area and wear gloves or wash your<br>For more information go to www.P65Warnings.ca.gov/passeng   |

2201903025636

