9-NORMAL, NB, 301757, RM023 14073 220241210 **4865**

U W NH C ULC CERT CERT CERT TRD RAMP BUMP CAMP BOOK EXFL ROTA

ford.com	F-150 2025 F-150 4X4 SUPERCREW 145" WHEELBASE 2.7L V6 ECOBOOST ELEC TEN-SPEED AUTO TRANS	INTERI	IOR FORD WHITE	18995	EPA DOT Fuel Economy and En Fuel Economy MPG Standard 84 MPG. MPGe.
STANDARD EQUIPMENT INCLUDED A EXTERIOR • DAYTIME RUNNING LAMPS • EASY FUEL® CAPLESS FILLER • FULLY BOXED STEEL FRAME • GRILLE - BLACK & DARK GRAY • HEADLAMPS - AUTO HIGH BEAM • HEADLAMPS - AUTO HIGH BEAM • HEADLAMPS - AUTOLAMP (ON/OFF) • LED REFLECTOR HEADLAMPS • POWER TAILGATE LOCK • REAR PRIVACY GLASS • TRAILER SWAY CONTROL • WIPERS- INTERMITTENT INCLUDED ON THIS VEHICLE EQUIPMENT GROUP 201A • STX SERIES • 118" BLACK PAINTED ALUMINUM WH • SKID PLATES • LINER-TRAY STYLE-NO CARPET MA • LED FOG LAMPS OPTIONAL EQUIPMENT/OTHER EXTENDED RANGE 36GAL FUEL TAN .LT265/70R18C BSW ALL-TERRAIN 3.55 ELECTRONIC LOCK RR AXLE 6650# GWWR PACKAGE FRONT LICENSE PLATE BRACKET 50 STATE EMISSIONS	IND EXTRA CHARGE INTERIOP CRUISE CONTROL DOAR LOCKS - POWER DUAL SUNVISORS ILLUMINATED ENTRY MESSAGE CTR: OUTSIDE TEMP, COMPASS, TRIP COMPUTER TILT/TELESCOPE STR COLUMN (MSRP) 3,715.00 NO CHARGE NO CHARGE	rol :	AIRBAGS - MOUNTED CH W/ INECTOR T 5GWI-FI MODEM W T W/AEB MODEM W SOS POST T W/AEB D SYR/60,000 SYR/60,000	TRAC™ WITH RSC® • FRONT SEAT SIDE IMPACT • SAFETY CANOPY® MOUNT STOP LAMP IR ALARM KG 1 YR INCLUDED • CRASH ALERT SYS™ SURE MONIT SYS 0 BUMPER / BUMPER 0 POWERTRAIN 0 ROADSIDE ASSIST (MSRP) \$51,130.00 3,715.00 THER 54,845.00 1,995.00	Image: State of the risk of injury in a final state of the risk of injury in a single-vehicle state of the risk of the risk of the risk of the risk state of the risk state.
	RAMP ONE CA8F RAMP TWO ITEM #:	CONVOY		\$53,840.00 ide to lease or finance your d the choices that are right dealer for details or visit	IFTEW2LP6SFA18995
	This label is affixed pursuant to the Federal Automobile Information Disclosure Act. Gasoline, License, and Title Fees, State and Local taxes are not included. Dealer installed options or accessories are not included unless listed above.		RM023 N RB 2X 535 001757 12 02 24		lead, which are known to the State of California to cause can To minimize exposure, avoid breathing exhaust, do not idle th vehicle in a well-ventilated area and wear gloves or wash you For more information go to www.P65Warnings.ca.gov/passer



2202412104865