KAN-001157 IL	9-NORMAL, NB, 201157, PE152	750 220230521 5557	CERTCERTCERT TRD RAMPBUMPC	
	5-150 2023 F-150 4X4 SUPERCAB 145" WHEELBASE 2.7L V6 ECOBOOST ELEC TEN-SPEED AUTO W/TO	EXTERIOR OXFORD WHIT INTERIOR W M BLACK SPORT	PK E49949	Fuel Economy and En Fuel Economy MPG Standard P 70 MPG. TI MPGe. 18 24
EXTERIOR • DAYTIME RUNNING LAMPS • EASY FUEL® CAPLESS FILLER • HALOGEN HEADLAMPS • HEADLAMPS - AUTO HIGH BEAM • HEADLAMPS - AUTOLAMP (ON/OFF) • LOCKING REMOVABLE TAILGATE • MANUAL FOLD POWER MIRRORS • PICKUP BOX TIE DOWN HOOKS • POWER TAILGATE LOCK • TRAILER SWAY CONTROL • WIPERS- INTERMITTENT INCLUDED ON THIS VEHICLE EQUIPMENT GROUP 101A • XL SERIES OPTIONAL EQUIPMENT/OTHER 2.7L V6 ECOBOOST 275/65R 18 BSW ALL-TERRAIN 3.73 ELECTRONIC LOCK RR AXLE 6500# GVWR PACKAGE FRONT LICENSE PLATE BRACKET STX APPEARANCE PACKAGE .SYNC 4 W/ENHANCED VOICE RECOG .REAR-WINDOW DEFROSTER .SIRIUS XM W/ 360L .PRIVACY GLASS W/REAR DEFROSTE 50 STATE EMISSIONS ONBOARD 400W OUTLET TRAILER TOW PACKAGE .INTEGRATED TRAILER BRAKE CONT FX4 OFF-ROAD PACKAGE .SKID PLATES 18" 6-SPOKE GLOSS BLACK WHEELS STX SPORT CLOTH 40/CON/40	<pre>NTERIOR</pre>	DESTINATION TOTAL BEF XL DISCOU	\$42,995.00 7,495.00 7,495.00 ************************************	combined city/hwy city highway 5.0 gallons per 100 miles Annual fuel COST \$\$2,2,2000 Image: Control of the second se
	RAMP ONE CF95	TOTAL	MSRP \$50,885.00	1FTEX1EP2PKE49949
	RAMP TWO	41-S702 OT 2 Ford Credit	Whether you decide to lease or finance your vehicle, you'll find the choices that are right for you. See your dealer for details or visit www.ford.com/finance.	WARNING: Operating, servicing and maintaining a pas vehicle can expose you to chemicals including engine of lead, which are known to the State of California to cause canc
	This label is affixed pursuant to Information Disclosure Act. Gas State and Local taxes are not in options or accessories are not i	the Federal Automobile soline, License, and Title Fees, cluded. Dealer installed PE152 N I	RB 2X 355 001157 05 15 23	To minimize exposure, avoid breathing exhaust, do not idle the vehicle in a well-ventilated area and wear gloves or wash your For more information go to www.P65Warnings.ca.gov/passeng

