

VEHICLE DESCRIPTION

F-150 RAPTOR

2025 RAPTOR 4X4 SUPERCREW
145" WHEELBASE
3.5L ECOBOOST HIGH OUTPUT
ELEC TEN-SPEED AUTO TRANS

EXTERIOR
AGATE BLACK METALLIC
INTERIOR
RECARO BLACK SEAT

SF B27931

STANDARD EQUIPMENT INCLUDED AT NO EXTRA CHARGE

EXTERIOR

- 5 LINK REAR SUSPENSION
- BUMPER - RAPTOR-UNIQUE FRONT PERFORMANCE
- DUAL EXHAUST SYSTEM W/DUAL TAILPIPES
- FUEL TANK - 36.0 GALLON
- HEADLAMPS - AUTO HIGH BEAM
- HEADLAMPS - AUTOLAMP (ON/OFF)
- LED PROJECTOR W/ DYNAMIC BENDING HEADLAMPS
- LED SIDE-MIRROR SPOTLIGHTS
- RIGID® LED FOG LAMP
- WHEEL LIP MOLDINGS

INTERIOR

- 12" PRODUCTIVITY SCREEN
- 2ND ROW HEATED SEATS
- A/C W/DUAL CLIMATE CONTROL
- ADAPTIVE CRUISE CONTROL
- COMPASS
- HEAD-UP DISPLAY
- HTD LTHR WRAPPED STR WHL
- HTD/VENTILATED FRT SEATS
- OUTSIDE TEMP DISPLAY
- PEDALS-PWR ADJ W/MEMORY
- POWER LOCKS AND WINDOWS
- RAPTOR BRANDED FLOOR MATS
- RAPTOR-UNIQUE CENTER STACK
- STEERING - TILT/TELESCOPIC WHEEL WITH AUDIO

FUNCTIONAL

- 360-DEGREE CAMERA
- B&O UNLEASHED, 14 SPKR
- BED UTILITY PKG
- FORDPASS™ CONNECT 5GWI-FI HOTSPOT TELEMATICS MODEM
- FOX LIVE VALVE SHOCKS
- MOBILE OFFICE PKG
- PRO TRAILER BACKUP ASSIST
- PRO TRAILER HITCH ASSIST
- REVERSE SENSING AND REAR VIEW CAMERA
- SKID PLATES
- SYNC®4 W/EVR & 12" SCREEN
- TERRAIN MANAGEMENT SYSTEM
- TRAIL CONTROL

SAFETY/SECURITY

- ADVANCETRAC™ WITH RSC®
- AIRBAGS - FRONT SEAT MOUNTED SIDE IMPACT
- AIRBAGS - SAFETY CANOPY®
- PERIMETER ALARM
- SECURE PKG 1 YR INCLUDED
- SOS POST-CRASH ALERT SYST™
- TIRE PRESSURE MONIT SYS

WARRANTY

- 3YR/36,000 BUMPER / BUMPER
- 5YR/60,000 POWERTRAIN
- 5YR/60,000 ROADSIDE ASSIST

INCLUDED ON THIS VEHICLE

(MSRP)

EQUIPMENT GROUP 802A

•RAPTOR SERIES

•17" CAST ALUM BEAD-LOCK CAPAB

•DUAL VALVE SHOCKS

11,470.00

PRICE INFORMATION

BASE PRICE

\$79,005.00

TOTAL OPTIONS/OTHER

13,560.00

TOTAL VEHICLE & OPTIONS/OTHER

92,565.00

DESTINATION & DELIVERY

1,995.00

(MSRP)

OPTIONAL EQUIPMENT/OTHER

.37 X 12.5R17 BSW ALL-TERRAIN

4.10 ELECTRONIC LOCK RR AXLE

7400# GVWR PACKAGE

FRONT LICENSE PLATE BRACKET

50 STATE EMISSIONS

TWIN PANEL MOONROOF

BEDLINER-TOUGHBED SPRAYIN*ACCY

NO CHARGE

NO CHARGE

1,495.00

595.00

	RAMP ONE		TOTAL MSRP \$94,560.00
	RA42	RAIL	
	RAMP TWO	ITEM #: 74-R06B O/T 2	
	This label is affixed pursuant to the Federal Automobile Information Disclosure Act. Gasoline, License, and Title Fees, State and Local taxes are not included. Dealer installed options or accessories are not included unless listed above.		SE121 N RB 2X 560 004018 05 12 25

EPA DOT

Fuel Economy and Environment

Gasoline Vehicle

Fuel Economy

16

combined city/hwy

14

city

18

highway

6.2 gallons per 100 miles

You spend

\$7,000

more in fuel costs over 5 years

compared to the average new vehicle.

Annual fuel cost

\$3,300

Fuel Economy & Greenhouse Gas Rating (tailpipe only)

Smog Rating (tailpipe only)

1310

Best

1610

Best

This vehicle emits 556 grams CO₂ per mile. The best emits 0 grams per mile (tailpipe only). Producing and distributing fuel also create emissions; learn more at fueleconomy.gov.

fueleconomy.gov

Calculate personalized estimates and compare vehicles

U.S. DEPARTMENT OF ENERGY

U.S. DEPARTMENT OF TRANSPORTATION

U.S. ENVIRONMENTAL PROTECTION AGENCY

GOVERNMENT 5-STAR SAFETY RATINGS

Overall Vehicle Score

★★★★★

Based on the combined ratings of frontal, side and rollover. Should ONLY be compared to other vehicles of similar size and weight.

Frontal Crash

Driver Passenger

★★★★★

Based on the risk of injury in a frontal impact. Should ONLY be compared to other vehicles of similar size and weight.

Side Crash

Front seat Rear seat

★★★★★

Based on the risk of injury in a side impact.

Rollover

★★★★

Based on the risk of rollover in a single-vehicle crash.

Star ratings range from 1 to 5 stars (★★★★★), with 5 being the highest. Source: National Highway Traffic Safety Administration (NHTSA). www.safercar.gov or 1-888-327-4236

1FTFW1RG2SFB27931

WARNING:

Operating, servicing and maintaining a passenger vehicle, pickup truck, v vehicle can expose you to chemicals including engine exhaust, carbon monoxide, phtl lead, which are known to the State of California to cause cancer and birth defects or other reproductive harm. To minimize exposure, avoid breathing exhaust, do not idle the engine except as necessary, service your vehicle in a well-ventilated area and wear gloves or wash your hands frequently when servicing your vehicle. For more information go to www.P65Warnings.ca.gov/passenger-vehicle.

rates may apply. Text HELP for help

www.ford.com/help/privacy-terms/

2202505206126