
FD

9-NORMAL, NB, 002731, SB191 **14808**

W 220250228 0423 CERT CERT TRD RAMPBUMP CAMPBOOK EXFL ROTA

FORD PERFORMANCE 2025 RA 3.5L EC	ON ORAPTO APTOR 4X4 SUPERCRE HEELBASE COBOOST HIGH OUTPU EN-SPEED AUTO TRAF	EW EXT S IT INTE	SF A	60287	EPA DOT Fuel Economy and E Fuel Economy Standard Standard Standard Standard Standard MPG MPGe.
BUMPER - RAPTOR-UNIQUE PRONT PERFORMANCE A/C W/DUA DUAL EXHAUST SYSTEM W/DUAL ADAPTIVE TAILPIPES COMPASS FUEL TANK - 36.0 GALLON HEADLAMPS - AUTO HIGH BEAM HTD LTHR HEADLAMPS - AUTOLAMP LED PROJECTOR W/ DYNAMIC LED PROJECTOR W/ DYNAMIC LED SIDE-MIRROR SPOTLIGHTS RIGID® LED FOG LAMP SUBMERDING HEADLAMP SUBMERDING HEADLAM	JCTIVITY SCREEN HEATED SEATS AL CLIMATE CONTROL CRUISE CONTROL DISPLAY WRAPPED STR WHL ILATED FRT SEATS TEMP DISPLAY WR ADJ W/MEMORY OCKS AND WINDOWS RANDED FLOOR MATS INIQUE CENTER STACK - TILT/TELESCOPIC TH AUDIO	EUNCTIONAL 9360-DEGREE CAMEI 980 UNLEASHED, 1 9ED UTILITY PKG FORDPASS™ CONN HOTSPOT TELEMAT 9FOX LIVE VALVE SHI 9FO TRAILER BACK 9FO TRAILER HITCH REVERSE SENSING REAR VIEW CAMERA 9KID PLATES 9YNC®4 W/EVR & 12 1TERRAIN MANAGEM 1TRAIL CONTROL	4 SPKR • AIRBAGS MOUNTEL ECT 5GWI-FI • AIRBAGS ICS MODEM • PERIMET OCKS • SECURE I G • SOS POS UP ASSIST • TIRE PRE 1 ASSIST AND <u>WARRANT</u> AND <u>VARRANT</u> A • 3YR/36,00 • 5YR/60,00	ETRAC [™] WITH RSC® - FRONT SEAT D SIDE IMPACT - SAFETY CANOPY® ER ALARM PKG 1 YR INCLUDED T-CRASH ALERT SYS [™] SSURE MONIT SYS Y 00 BUMPER / BUMPER 00 POWERTRAIN 00 ROADSIDE ASSIST (MSRP) \$79,005.00 13,975.00	Image: Section 1.1.1.1.1.1.1.1.1.1.1.1.1.1.1.1.1.1.1.
	RAMP ONE CA8F	CONVOY 11-C001 O/T 2	TOTAL MSRP Whether you de vehicle, you'll fir for you. See you www.ford.com/	\$94,975.00 cide to lease or finance your nd the choices that are right r dealer for details or visit finance	WARNING: Operating, servicing and maintaining a vehicle can expose you to chemicals including enging lead, which are known to the State of California to cause ca
	This label is affixed pursuant to Information Disclosure Act. Ga State and Local taxes are not ir options or accessories are not	asoline, License, and Title Fees, ncluded. Dealer installed	SB191 N RB 2X 550 0		lead, which are known to the State of California to cause ca To minimize exposure, avoid breathing exhaust, do not idle vehicle in a well-ventilated area and wear gloves or wash y For more information go to www.P65Warnings.ca.gov/pass



2202502280423