FD

220250423 3561 BLEND

ford.com	-150 2025 F-150 4X4 SUPERC 145" WHEELBASE 5.0L V8 ENGINE ELEC TEN-SPEED AUTO	S INTE	SK ERIOR SPACE WHITE METALLIC ERIOR SMOKED TRUFFLE 40/CO		EPA DOT Fuel Economy and Er Fuel Economy Standard I Fuel Economy MPG MPGe MPGe
EXTERIOR • DAYTIME RUNNING LAMPS • EASY FUEL® CAPLESS FILLER • FULLY BOXED STEEL FRAME • HEADLAMPS - AUTO HIGH BEAM • HEADLAMPS - AUTOLAMP (ON/OFF) • LED REFLECTOR HEADLAMPS • PICKUP BOX TIE DOWN HOOKS • POWER TAILGATE LOCK • REAR PRIVACY GLASS • TRAILER SWAY CONTROL • WIPERS- INTERMITTENT • ZONE LIGHTING INCLUDED ON THIS VEHICLE EQUIPMENT GROUP 301A • XLT SERIES •8-WAY POWER DRIVERS SEAT • DUAL ZONE AUTO TEMP CONTROL OPTIONAL EQUIPMENT/OTHER LED FOG LAMPS 5.0L V8 ENGINE 275/65R 18 BSW ALL-TERRAIN 3.31 ELECTRONIC LOCK RR AXLE FRONT LICENSE PLATE BRACKET 6" BRIGHT ANODIZED STEP BAR	INTERIOR • 12" PRODUCTIVITY SCREEN • DOOR LOCKS - POWER • DUAL SUNVISORS • ILLUMINATED ENTRY • MESSAGE CTR: OUTSIDE TEMP COMPASS, TRIP COMPUTER • TILT/TELESCOPE STR COLUMN (MSRP) 1,585.00	HOTSPOT TELEMAT	ADVAN AFFIC ALERT HITCH W/ CONNECTOR AIRBAC MOUNT CONNECTOR AIRBAC CTR HIL CTR HIL CTR HIL CTR HIL CTR HIL SECUR SOS PC SIST W/AEB SIST AND A SIST AND A SIST AND A SIST AND SIST AND A SIST AND SIST SIST SIST AND SIST AND SIST AND SIST SIST	,000 BUMPER / BUMPER ,000 POWERTRAIN ,000 ROADSIDE ASSIST 0,000 HYBRID BATTERY (MSRP) \$51,915.00 5,785.00	indication 16 24 highway 6.3 gallons per 100 miles indication 5.3 gallons per 100 miles indication indication 10 indication indication
	CATB	CONVOY	TOTAL MSRP	\$59,695.00 decide to lease or finance your	1FTFW3L57SKE16796
	This label is affixed purs Information Disclosure A State and Local taxes an	CONVOY ITEM #: 52-6488 O/T 2 uant to the Federal Automobile Act. Gasoline, License, and Title Fees, e not included. Dealer installed re not included unless listed above.	(Ford) vehicle you'll	find the choices that are right our dealer for details or visit n/finance.	WARNING: Operating, servicing and maintaining a pa vehicle can expose you to chemicals including engine lead, which are known to the State of California to cause can To minimize exposure, avoid breathing exhaust, do not idle th vehicle in a well-ventilated area and wear gloves or wash you For more information go to www.P65Warnings.ca.gov/passer



2202504233561