KAN-004191 _{TN}	9-NORMAL,NB,204191,SA212 7893	3 220250129 2731	ULC U W TN CERT CERT CERT TRD RAMP BUMP C	C 296
Ford.com	ICLE DESCRIPTION F-150 2025 F-150 4X4 SUPERCREW 145" WHEELBASE 3.5L V6 ECOBOOST ELEC TEN-SPEED AUTO TRANS	INTERIOR	SK D41614 GRAY METALLIC ATE CLOTH 40/C/40	EPA DOT Fuel Economy Fuel Economy Fuel Economy MPG MPGe.
STANDARD EQUIPMENT INCLUDED A EXTERIOR • DAYTIME RUNNING LAMPS • EASY FUEL® CAPLESS FILLER • FULLY BOXED STEEL FRAME • HEADLAMPS - AUTO HIGH BEAM • HEADLAMPS - AUTOLAMP (ON/OFF) • LED REFLECTOR HEADLAMPS	INTERIOR • 12" PRODUCTIVITY SCREEN • DOOR LOCKS - POWER • DUAL SUNVISORS • ILLUMINATED ENTRY • MESSAGE CTR: OUTSIDE TEMP, COMPASS, TRIP COMPUTER • TILT/TELESCOPE STR COLUMN	EUNCTIONAL • AUTO HOLD • BLIS W/CROSS-TRAFFIC ALERT • CLASS IV TRAILER HITCH W/ SMART TRLR TOW CONNECTOR • FORDPASS™ CONNECT 5GWI-FI HOTSPOT TELEMATICS MODEM • LANE-KEEPING SYSTEM	 SAFETY/SECURITY ADVANCETRAC™ WITH RSC® AIRBAGS - FRONT SEAT MOUNTED SIDE IMPACT AIRBAGS - SAFETY CANOPY® CTR HIGH MOUNT STOP LAMP PERIMETER ALARM SECURE PKG 1 YR INCLUDED 	combined city/hwy city highway 5.3 gallons per 100 miles
 PICKUP BOX TIE DOWN HOOKS POWER TAILGATE LOCK REAR PRIVACY GLASS TRAILER SWAY CONTROL WIPERS- INTERMITTENT ZONE LIGHTING 		POST-COLLISION BRAKING PRE-COLLISION ASSIST W/AEB REVERSE BRAKE ASSIST REVERSE SENSING AND REAR VIEW CAMERA SELECTABLE DRIVE MODES SYNC®4 W/EVR & 12" SCREEN	SOS POST-CRASH ALERT SYS™ TIRE PRESSURE MONIT SYS <u>WARRANTY</u> 3YR/36,000 BUMPER / BUMPER 5YR/60,000 POWERTRAIN 5YR/60,000 ROADSIDE ASSIST 8YR/100,000 HYBRID BATTERY	Annual fuel COSt \$2,750 This vehicle emits 4 distributing fuel also
INCLUDED ON THIS VEHICLE EQUIPMENT GROUP 302A •XLT SERIES •LED SIDE-MIRROR SPOTLIGHTS	(MSRP) 7,440.00	PRICE INFO BASE PRICE TOTAL OPTIC	(MSRP) RMATION \$51,815.00	Actual results will vary for many reasons, including driving vehicle. The average new vehicle gets 28 MPG and costs \$9, based on 15,000 miles per year at \$3.50 per gallon. MPGe is emissions are a significant cause of climate change and smoother structure of the
•POWER-SLIDING REAR WINDOW		TOTAL VEHIC	LE & OPTIONS/OTHER 62.795.00	

OPTIONAL EQUIPMENT/OTHER		
3.5L V6 ECOBOOST	1,660.00	
275/65R18 BSW ALL-TERRAIN TIRE		
3.55 ELECTRONIC LOCK RR AXLE	NO CHARGE	
7100# GVWR PACKAGE		
6" BRIGHT ANODIZED STEP BAR		
50 STATE EMISSIONS	NO CHARGE	
TOW/HAUL PACKAGE	785.00	
.INTEGRATED TRAILER BRAKE CONT		
MIRROR MAN FOLD W/POWER GLASS		
FX4 OFF-ROAD PACKAGE	1,095.00	
.SKID PLATES		
.LINER-TRAY STYLE-NO CARPET MA		

18" CHROME-LIKE PVD WHEELS EXTENDED RANGE 36GAL FUEL TANK						
		RAMP ONE		τοται	MSRP	\$62,790.00
		CH32				402 ,730.00
	RAMP TWO	CONVOY	Ford	Whether you de	you decide to lease or finance your ou'll find the choices that are right	
			ITEM #: 47-Z415 O/T 2	Ford Credit	for you. See your dealer for details or visit	

This label is affixed pursuant to the Federal Automobile

Information Disclosure Act. Gasoline, License, and Title Fees, State and Local taxes are not included. Dealer installed SA212 N RB 2X 545 004191 01 21 25 options or accessories are not included unless listed above.

www.ford.com/finance.

DESTINATION & DELIVERY

XLT MID DISCOUNT

TOTAL SAVINGS

TOTAL BEFORE DISCOUNTS

1,995.00

64,790.00

2,000.00

- 2,000.00

 $\star \star \star \star$ Rollover Based on the risk of rollover in a single-vehicle crash Star ratings range from 1 to 5 stars (★★★★), with 5 being the highest. Source: National Highway Traffic Safety Administration (NHTSA). www.safercar.gov or 1-888-327-4236 1FTFW3L82SKD41614

Driver

Passenger

Front seat

Rear seat

Based on the risk of injury in a side impact

Overall Vehicle Score


Frontal

Crash

Side

Crash

WARNING: Operating, servicing and maintaining a passenger vehicle, pickup truck, v vehicle can expose you to chemicals including engine exhaust, carbon monoxide, pht lead, which are known to the State of California to cause cancer and birth defects or other reproductive narm. To minimize exposure, avoid breathing exhaust, do not idle the engine except as necessary, service your vehicle in a well-ventilated area and wear gloves or wash your hands frequently when servicing your vehicle. For more information go to www.P65Warnings.ca.gov/passenger-vehicle.



2202501292731