FD

220250422 7056 BLEND 7056

U W MI ULC CERT CERT CERT TRD RAMP BUMP CAMP BOOK EXFL ROTA

Ford.com	F-150 2025 F-150 4X4 SUPERCREW 145" WHEELBASE 3.5L POWERBOOST FULL HYE HYBRID ELEC 10-SPD AUTO	CARBON BRID INTERIOR	SF A98		EPA DOT Fuel Economy and En Fuel Economy MPG Standard P 87 MPG. T MPGe.
STANDARD EQUIPMENT INCLUDED A EXTERIOR • DAYTIME RUNNING LAMPS • EASY FUEL® CAPLESS FILLER • FULLY BOXED STEEL FRAME • HEADLAMPS - AUTO HIGH BEAM • HEADLAMPS - AUTOLAMP (ON/OFF) • LED REFLECTOR HEADLAMPS • PICKUP BOX TIE DOWN HOOKS • POWER TAILGATE LOCK REAR PRIVACY GLASS • TRAILER SWAY CONTROL • WIPERS- INTERMITTENT • ZONE LIGHTING INCLUDED ON THIS VEHICLE EQUIPMENT GROUP 302A • XLT SERIES • LED SIDE-MIRROR SPOTLIGHTS • POWER-SLIDING REAR WINDOW OPTIONAL EQUIPMENT/OTHER 3.5L POWERBOOST FULL HYBRID HYBRID ELEC 10-SPD AUTO TRANS 3.73 ELECTRONIC LOCK RR AXLE 7400# GVWR PACKAGE XLT BLACK APPEARANCE PACKAGE .275/65R 18 BSW ALL-TERRAIN .18" GLOSS BLACK WHEELS 50 STATE EMISSIONS FLOOR LINER - TRAY STYLE MOBILE OFFICE PACKAGE .WIRELESS CHARGING PAD MIRROR MAN FOLD W/POWER GLASS STANDARD FUEL TANK DEALER INSTALLED OPTIONS SecuriCodeÖ Wireless Keyless E	INDEXTRA CHARGE INTERIOR 12" PRODUCTIVITY SCREEN DOAL SUNVISORS 11LLUMINATED ENTRY MESSAGE CTR: OUTSIDE TEMP, COMPASS, TRIP COMPUTER TILT/TELESCOPE STR COLUMN (MSRP) 7,440.00 3,560.00 NO CHARGE 595.00 NO CHARGE 200.00 555.00 225.00	BASE I TOTAL DESTIN TOTA XLT M POWE	MOUNTED SIDE IM OR AIRBAGS - SAFET II-FI CTR HIGH MOUNT EM PERIMETER ALAR SECURE PKG 1 YF SOS POST-CRASH EB TIRE PRESSURE M <u>WARRANTY</u> 3YR/36,000 BUMP 5YR/60,000 POWE N 5YR/60,000 POWE 8YR/100,000 HYBF	WITH RSC® F SEAT MPACT Y CANOPY® F STOP LAMP M R INCLUDED H ALERT SYS™ MONIT SYS PER / BUMPER ERTRAIN SIDE ASSIST	Image: Start Sta
	RAMP ONE CM59 RAMP TWO ITEM # This label is affixed pursuant to	CONVOY 48-093E O/T 2 Ford C	Whether you decide to le vehicle, you'll find the ch	oices that are right	<b>IFTFW3LD5SFA98936</b> WARNING: Operating, servicing and maintaining a part vehicle can expose you to chemicals including engine lead, which are known to the State of California to cause cand To minimize exposure, avoid breathing exhaust, do not idle the vehicle in a well-ventilated area and wear gloves or wash you



2202504227056