FD

9-NORMAL, NB, 102524, SD111 2169

220250422 1793 BLEND

U W TN ULC CERT CERT CERT TRD RAMP BUMP CAMP BOOK EXFL ROTA

14		F INTE	SK ERIOR RAPID RED MET TINTE ERIOR SLATE ACTIVE X	E16020	EPA DOT Fuel Economy Fuel Economy Fuel Economy MPG Standard P 87 MPG. T
 FULLY BOXED STEEL FRAME FULLY BOXED STEEL FRAME HEADLAMPS - AUTO HIGH BEAM HEADLAMPS - AUTOLAMP (ON/OFF) LED PROJECTOR W/ DYNAMIC BENDING HEADLAMPS LED SIDE-MIRROR SPOTLIGHTS LED TAIL LAMPS POWER MIRRORS REMOTE TAILGATE RELEASE TRAILER SWAY CONTROL INCLUDED ON THIS VEHICLE (M EQUIPMENT GROUP 501A LARIAT SERIES OPTIONAL EQUIPMENT/OTHER 2025 MODEL YEAR RAPID RED MET TINTED CC 3.5L V6 ECOBOOST 2100# GVWR PACKAGE FRONT LICENSE PLATE BRACKET 6" BRIGHT ANODIZED STEP BAR 50 STATE EMISSIONS NO CH TWIN PANEL MOONROOF LARIAL 	AVAY PWR DRV & MULTI-ADJ FRT PASS PRODUCTIVITY SCREEN W/DUAL CLIMATE CONTROL IVEX SEATING MATERIAL PTIVE CRUISE CONTROL O DIM REARVIEW MIRROR PREM WRAPPED STR WHL /VENTILATED FRT SEATS B DRIVER/PASS LUMBAR SRP) 70.00 95.00 ARGE 95.00 ARGE	EUNCTIONAL 9 360-DEGREE CAMEH 9 BLIS W/CROSS-TRA 9 FORDPASS™ CONN HOTSPOT TELEMAT 1 INTELLIGENT ACCES BUTTON START 1 LANE-KEEPING SYS 9 POST-COLLISION AS 9 PRE-COLLISION AS 9 REVERSE BRAKE AS 9 REVERSE SENSING REAR VIEW CAMERA 9 SIRIUSXM® W/360L 1 SYNC®4 W/EVR & 1	RA • ADV/ IFFIC ALERT • AIRB IECT 5GWI-FI MOU ICS MODEM • AIRB SS W/PUSH • CTR • SECU STEM • SECU • SEU • SEU • SEU • SUST • MARE • SYR/ • SYR/	(36,000 BUMPER / BUMPER (60,000 POWERTRAIN (60,000 ROADSIDE ASSIST (100,000 HYBRID BATTERY (MSRP) \$63,360.00 8 5,840.00 ONS/OTHER 69,200.00	Image: A state of the stat
	RAMP ONE CH32 RAMP TWO		(Jord) vehicle voi	P \$71,195.00 ou decide to lease or finance your u'll find the choices that are right e your dealer for details or visit	IFTFW5L84SKE16020 WARNING: Operating, servicing and maintaining a pase you to chomicals including opains
	State and Local taxes are not	Basoline, License, and Title Fees,	www.tora.c	55 002524 04 11 25	WARNING: Operating, servicing and maintaining a pas vehicle can expose you to chemicals including engine e lead, which are known to the State of California to cause canc To minimize exposure, avoid breathing exhaust, do not idle the vehicle in a well-ventilated area and wear gloves or wash your For more information go to www.P65Warnings.ca.gov/passeng



2202504221793