FD

9-NORMAL, NB, 103248, SG151 9466

220250724 3566 BLEND

U W TX ULC CERTCERTCERT TRD RAMPBUMPCAMPBOOKEXFLROTABATT

	ICLE DESCRIPTION F-150 2025 F-150 4X4 SUPERCREW 145" WHEELBASE 3.5L POWERBOOST FULL HYBF HYB ELEC TEN-SPEED AUTO T	RID INTERIOR	SF B68518 TE METALLIC TRICOAT TIVE X	EPA DOT Fuel Economy and Er Fuel Economy R D D MPG Standard 87 MPG. MPGe.
STANDARD EQUIPMENT INCLUDED A EXTERIOR • DAYTIME RUNNING LAMPS • FULLY BOXED STEEL FRAME • HEADLAMPS - AUTO HIGH BEAM • HEADLAMPS - AUTOLAMP (ON/OFF) • LED PROJECTOR W/ DYNAMIC BENDING HEADLAMPS • LED SIDE-MIRROR SPOTLIGHTS • LED TAIL LAMPS • POWER MIRRORS • REMOTE TAILGATE RELEASE • TRAILER SWAY CONTROL INCLUDED ON THIS VEHICLE EQUIPMENT GROUP 501A • LARIAT SERIES OPTIONAL EQUIPMENT/OTHER 2025 MODEL YEAR STAR WHITE METALLIC TRICOAT 3.5L POWERBOOST FULL HYBRID HYB ELEC TEN-SPEED AUTO TRANS 275/60R20 BSW ALL-TERRAIN 3.73 MAX TOW E-LOCK REAR AXLE 7400# GVWR PACKAGE FRONT LICENSE PLATE BRACKET 6" BRIGHT ANODIZED STEP BAR 50 STATE EMISSIONS BLUECRUISE EQUIP: 90DAY TRIAL TOW/HAUL PACKAGE INTEGRATED TRAILER BRAKE CONT FX4 OFF-ROAD FUEL TANK	AT NO EXTRA CHARGE INTERIOR	BASE PRI TOTAL OI TOTAL VE DESTINAT TOTAL POWER	MOUNTED SIDE IMPACT AIRBAGS - SAFETY CANOPY® CTR HIGH MOUNT STOP LAMP SECURE PKG 1 YR INCLUDED SECURILOCK® ANTI-THEFT SYS SOS POST-CRASH ALERT SYS™ TIRE PRESSURE MONIT SYS WARRANTY 3YR/36,000 BUMPER / BUMPER 5YR/60,000 POWERTRAIN 5YR/60,000 ROADSIDE ASSIST 8YR/100,000 HYBRID BATTERY (MSRP)	Image: Additional state of the state of
	RAMP ONE RH80 RAMP TWO ITEM #:	RAIL Scan get m	AL MSRP \$71,435.00 The QR Code to	1FTFW5LD4SFB68518
	This label is affixed pursuant to the Information Disclosure Act. Gase State and Local taxes are not include options or accessories are not include the Information Disclosure Act.	he Federal Automobile Jline, License, and Title Fees, uded. Dealer installed SG151	N RB 2X 565 003248 07 15 25	lead, which are known to the State of California to cause can To minimize exposure, avoid breathing exhaust, do not idle th vehicle in a well-ventilated area and wear gloves or wash you For more information go to www.P65Warnings.ca.gov/passer



2202507243566