FD

9-NORMAL, NB, 104174, SC311 7319

220250408 6869 BLEND

	CLE DESCRIPTION F-150 2025 F-150 4X4 SUPERCREW 145" WHEELBASE 3.5L POWERBOOST FULL HYBR HYBRID ELEC 10-SPD AUTO TR	RID INTERIO	DR CE WHITE METALLIC	5076	EPA DOT Fuel Economy and En Fuel Economy MPG Standard F 84 MPG. T
STANDARD EQUIPMENT INCLUDED A EXTERIOR • BUMPERS- BODY COLOR • LED FOG LAMPS • LED PROJECTOR W/ DYNAMIC BENDING HEADLAMPS • LED SIDE-MIRROR SPOTLIGHTS • LED TAIL LAMPS • POWER MIRRORS • POWER MIRRORS • POWER SLIDING REAR WINDOW W/DEFROST & PRIVACY TINT • REMOTE TAILGATE RELEASE • RUNNING BOARD-PWR DEPLOY INCLUDED ON THIS VEHICLE EQUIPMENT GROUP 702A •PLATINUM SERIES • B&O UNLEASHED SOUND SYS 14SPK • TWIN PANEL MOONROOF OPTIONAL EQUIPMENT/OTHER 20" PAINTED GLOSS EBONY BLACK 3.5L POWERBOOST FULL HYBRID HYBRID ELEC 10-SPD AUTO TRANS .275/60R20 BSW ALL-TERRAIN 3.73 ELECTRONIC LOCK RR AXLE 7400# GVWR PACKAGE FRONT LICENSE PLATE BRACKET 50 STATE EMISSIONS PRO POWER ONBOARD - 7.2KW BLUECRUISE EQUIP: 1 YEAR PLAN F44 OFF-ROAD PACKAGE .SKID PLATES .FLOOR LINER - TRAY STYLE STANDARD FUEL TANK	SUBJECT OF CONTROL OF	BA TC DE TC PC	5GWI-FI AODEM I START START • AIRBAGS - SAF • LED CTR HIGH • SECURE PKG 1 • SECURILOCK® • SOS POST-CRA • TIRE PRESSUR • WARRANTY • 3YR/36,000 BUI	C TM WITH RSC® DNT SEAT E IMPACT TETY CANOPY® MNT STOP LAMP YR INCLUDED ANTI-THEFT SYS ASH ALERT SYS™ IE MONIT SYS MPER / BUMPER WERTRAIN ADSIDE ASSIST YBRID BATTERY (MSRP) \$74,905.00 9,535.00 R 84,440.00 1,995.00 36,435.00	MPGe. August August Au
	RAMP ONE CH02 RAMP TWO	CONVOY	Whether you decide to	choices that are right	WARNING: Operating, servicing and maintaining a part vehicle can expose you to chemicals including engine lead, which are known to the State of California to cause cance
	This label is affixed pursuant to the Information Disclosure Act. Gase State and Local taxes are not inclu- options or accessories are not in	he Federal Automobile oline, License, and Title Fees, luded. Dealer installed	SC311 N RB 2X 555 004174		lead, which are known to the State of California to cause cance To minimize exposure, avoid breathing exhaust, do not idle the vehicle in a well-ventilated area and wear gloves or wash you For more information go to www.P65Warnings.ca.gov/passen



2202504086869