9-NORMAL, NB, 005413, RJ242 19545 220241003 5412 CERT CERT CERT TRD RAMP BUMP CAMP BOOK EXFL ROTA

W

	e description -150 2024 F-150 4X4 REGUL 141" WHEELBASE 2.7L V6 ECOBOOST ELEC TEN-SPEED AUTO	C INTE	RK F ERIOR DXFORD WHITE ERIOR DARK SLATE VINYL 40/20/	17925	EPA DOT Fuel Economy and E Fuel Economy MPG Standard 73 MPG. MPGe.
EXTERIOR • DAYTIME RUNNING LAMPS • EASY FUEL® CAPLESS FILLER • FULLY BOXED STEEL FRAME • HEADLAMPS - AUTO HIGH BEAM • HEADLAMPS - AUTOLAMP (ON/OFF) • LED REFLECTOR HEADLAMPS • LOCKING REMOVABLE TAILGATE • MANUAL FOLD POWER MIRRORS • PICKUP BOX TIE DOWN HOOKS • POWER TAILGATE LOCK • TRAILER SWAY CONTROL • WIPERS- INTERMITTENT INCLUDED ON THIS VEHICLE EQUIPMENT GROUP 101A • XL SERIES OPTIONAL EQUIPMENT/OTHER .17" SILVER STEEL WHEELS .265/70R 17 BSW ALL-TERRAIN 3.55 ELECTRONIC LOCK RR AXLE 6450# GVWR PACKAGE FRONT LICENSE PLATE BRACKET SKID PLATES 50 STATE EMISSIONS EXTENDED RANGE 36GAL FUEL TANK INTEGRATED TRAILER BRAKE CONT	INTERIOR • 12" PRODUCTIVITY SCREEN • CRUISE CONTROL • DOOR LOCKS - POWER • DUAL SUNVISORS • ILLUMINATED ENTRY • MESSAGE CTR: OUTSIDE TEN COMPASS, TRIP COMPUTER • POWERPOINTS - 12V • TILT/TELESCOPE STR COLUM (MSRP) 470.00 NO CHARGE 160.00 NO CHARGE 275.00 NO CHARGE 595.00	HOTSPOT TELEMAT • HILL START ASSIST	FFIC ALERT AIRBAGS MOUNTED CONNECTOR ECT 5GWI-FI ICS MODEM TEM RAKING SIST W/AEB AND A SIST W/AEB AND A A SIST W/AEB AND A SIST W/AEB AND A SIST W/AEB AND A A SIST W/AEB A A A A A A A A A A A A A	ETRAC [™] WITH RSC® 5 - FRONT SEAT D SIDE IMPACT 5 - SAFETY CANOPY® H MOUNT STOP LAMP ER ALARM 1T-CRASH ALERT SYS [™] VEH SVCS: 1 YR PLAN SSURE MONIT SYS TY 00 BUMPER / BUMPER 00 POWERTRAIN 00 ROADSIDE ASSIST 000 HYBRID BATTERY (MSRP) \$41,990.00 1,500.00	Image:
	RAMP ONE CK8P RAMP TWO			\$45,485.00 ecide to lease or finance your nd the choices that are right or dealer for details or visit	IFTMF1LP5RKF17925
	Information Disclosure State and Local taxes	47-1556 O/T LM Insuant to the Federal Automobile e Act. Gasoline, License, and Title Fees, are not included. Dealer installed is are not included unless listed above.	RJ242 N RB 2X 460 0		lead, which are known to the State of California to cause car To minimize exposure, avoid breathing exhaust, do not idle t vehicle in a well-ventilated area and wear gloves or wash yo For more information go to www.P65Warnings.ca.gov/passe



2202410035412