KTP-003889 <sub>TX</sub>	9-NORMAL, NB, 103889, RA161	088	CERT CERT CERT TRD RAMP BUMP C	CAMPBOOKEXFLROTA 2991/
	CLE DESCRIPTION SUPER DUT 2024 F350 SRW 4X2 REG CA XL 142" WB STYLESIDE 6.7 HI OUTPUT POWER STRO 10-SPEED AUTO TOROSHIFT	B EXTERIOR OXFORD WHIT DKE INTERIOR	RE DO8283	California Air Resources Board Environmen
STANDARD EQUIPMENT INCLUDED AT EXTERIOR • DOOR HANDLES - BLACK • HEADLAMPS - AUTOLAMP (ON/OFF) • TOW HOOKS • TRAILER BRAKE CONTROLLER • TRAILER SWAY CONTROL • TRAILER TOW MIRRORS • WIPERS- INTERMITTENT INCLUDED ON THIS VEHICLE OPTIONAL EQUIPMENT/OTHER PREFERRED EQUIPMENT PKG.610A 6.7 HI OUTPUT POWER STROKE 10-SPEED AUTO TORQSHIFT 3.31 RATIO REGULAR AXLE FRONT LICENSE PLATE BRACKET FORD PRO UPFIT INTEGRATION SYS 11100# GVWR PACKAGE 50 STATE EMISSIONS BLIS (BLIND SPOT INFO SYSTEM) JACK 410 AMP ALTERNATOR REVERSE SENSING SYSTEM DUAL BATTERY 360-DEGREE CAMERA PACKAGE XL DRIVER ASSIST PACKAGE	INCERTER CHARGE PARTICULATE AIR FILTER POWER LOCKS AND WINDOWS PARTICULATE AIR FILTER POWER LOCKS AND WINDOWS STEERING:TILT/TELESCOPE, CRUISE & AUDIO CONTROLS (MSRP) 12,495.00 NO CHARGE NO CHARGE NO CHARGE NO CHARGE 115.00 NO CHARGE 115.00 NO CHARGE 115.00 T30.00	<ul> <li>EUNCTIONAL</li> <li>4-WHEEL ANTILOCK BRAKE SYS</li> <li>FORDPASS™ CONNECT 5GWI-FI HOTSPOT TELEMATICS MODEM</li> <li>HILL START ASSIST</li> <li>REAR VIEW CAMERA</li> <li>SYNC®4 W/8" SCREEN</li> <li>TWIN I-BEAM INDEPENDENT FRT SUSPENSION W/STAB BAR</li> </ul>	\$46,015.00 14,890.00 LE & OPTIONS/OTHER 60,905.00	These ratings are not directly comparable the For information on how to compare Protect the environment. Cheen the environment of the envit of the environment of the
	RAMP ONE RK34 RAMP TWO	Ford	Whether you decide to lease or finance your vehicle, you'll find the choices that are right	1FTRF3AM8RED08283         WARNING: Operating, servicing and maintaining a passe
	This label is affixed pursuant t		for you. See your dealer for details or visit www.ford.com/finance.	WARNING: Operating, servicing and maintaining a passer vehicle can expose you to chemicals including engine exh lead, which are known to the State of California to cause cancer To minimize exposure, avoid breathing exhaust, do not idle the e vehicle in a well-ventilated area and wear gloves or wash your ha For more information go to www.P65Warnings.ca.gov/passenger

