



ford.com

VEHICLE DESCRIPTION

SUPER DUTY

2024 F350 SRW 4X2 REG CAB  
XL 142" WB STYLESIDE  
6.7 HI OUTPUT POWER STROKE  
10-SPEED AUTO TORQSHIFT

EXTERIOR  
OXFORD WHITE  
INTERIOR  
MEDIUM DARK SLATE VINYL

RE D08146

STANDARD EQUIPMENT INCLUDED AT NO EXTRA CHARGE

EXTERIOR

- DOOR HANDLES - BLACK
- HEADLAMPS - AUTOLAMP (ON/OFF)
- TOW HOOKS
- TRAILER BRAKE CONTROLLER
- TRAILER SWAY CONTROL
- TRAILER TOW MIRRORS
- WIPERS- INTERMITTENT

INTERIOR

- 4.2" PRODUCTIVITY SCREEN
- AIR COND, MANUAL FRONT
- CLOTH SUN VISORS
- DRIVER SEAT-MANUAL LUMBAR
- OUTSIDE TEMP DISPLAY
- PARTICULATE AIR FILTER
- POWER LOCKS AND WINDOWS
- STEERING:TILT/TELESCOPE, CRUISE & AUDIO CONTROLS

FUNCTIONAL

- 4-WHEEL ANTILOCK BRAKE SYS
- FORDPASS™ CONNECT 5GWI-FI HOTSPOT TELEMATICS MODEM
- HILL START ASSIST
- REAR VIEW CAMERA
- REMOTE KEYLESS ENTRY
- SYNC@4 W/8" SCREEN
- TWIN I-BEAM INDEPENDENT FRT SUSPENSION W/STAB BAR

SAFETY/SECURITY

- ADVANCETRAC™ WITH RSC®
- AIRBAGS - SAFETY CANOPY®
- BELT-MINDER CHIME
- DRIVER/PASSENGER AIR BAGS
- SECURILOCK® ANTI-THEFT SYS
- SOS POST-CRASH ALERT SYS™

WARRANTY

- 3YR/36,000 BUMPER / BUMPER
- 5YR/100,000 DIESEL ENGINE
- 5YR/60,000 POWERTRAIN
- 5YR/60,000 ROADSIDE ASSIST

INCLUDED ON THIS VEHICLE

OPTIONAL EQUIPMENT/OTHER

PREFERRED EQUIPMENT PKG.610A

6.7 HI OUTPUT POWER STROKE

10-SPEED AUTO TORQSHIFT

3.31 RATIO REGULAR AXLE

FRONT LICENSE PLATE BRACKET

FORD PRO UPFIT INTEGRATION SYS

11100# GVWR PACKAGE

50 STATE EMISSIONS

SPARE TIRE AND WHEEL DELETE

BLIS (BLIND SPOT INFO SYSTEM)

WHEEL WELL LINERS - FRONT

410 AMP ALTERNATOR

EXTERIOR BACKUP ALARM

REVERSE SENSING SYSTEM

TAILGATE STEP

DUAL BATTERY

360-DEGREE CAMERA PACKAGE

XL DRIVER ASSIST PACKAGE

(MSRP)

12,495.00

NO CHARGE

NO CHARGE

NO CHARGE

400.00

NO CHARGE

- 85.00

180.00

115.00

175.00

375.00

NO CHARGE

1,150.00

730.00

PRICE INFORMATION

BASE PRICE

\$46,015.00

TOTAL OPTIONS/OTHER


15,535.00

TOTAL VEHICLE & OPTIONS/OTHER

61,550.00

DESTINATION & DELIVERY

1,995.00

	RAMP ONE		TOTAL MSRP \$63,545.00
	RK34	RAIL	
	RAMP TWO	ITEM #: 52-Z505 O/T 2	<div><div></div><div>Ford Credit</div><div>Whether you decide to lease or finance your vehicle, you'll find the choices that are right for you. See your dealer for details or visit <a href="http://www.ford.com/finance">www.ford.com/finance</a>.</div></div>
	This label is affixed pursuant to the Federal Automobile Information Disclosure Act. Gasoline, License, and Title Fees, State and Local taxes are not included. Dealer installed options or accessories are not included unless listed above.		
			RA171 N RB 2X 425 002311 01 17 24

California Air Resources Board

Diesel Vehicle

Environmental Performance

These ratings are not directly comparable to the U.S. EPA/DOT light-duty vehicle label ratings. For information on how to compare, please see [www.arb.ca.gov/ep\\_label](http://www.arb.ca.gov/ep_label).

Protect the environment. Choose vehicles with higher ratings:

Greenhouse Gas Rating (tailpipe only)

A+

C-

D

Cleaner

Smog Rating (tailpipe only)

A+

B

D

Cleaner

Vehicle emissions are a primary contributor to climate change and smog. Ratings are determined by the California Air Resources Board based on this vehicle's measured emissions.



The FordPass® Connect modem is active and sending vehicle data (e.g., diagnostics) to Ford.\*\* See in-vehicle settings for connectivity options.

\*Based on 1977–2022 CY total sales.  
\*\*FordPass Connect (optional on select vehicles), the FordPass App and complimentary Connected Service are required for remote features (see FordPass Terms for details). Connected service and features depend on compatible AT&T network availability. Evolving technology/cellular networks/vehicle capability may limit functionality and prevent operation of connected features. Connected service excludes Wi-Fi hotspot.

1FTRF3AM9RED08146





WARNING:

Operating, servicing and maintaining a passenger vehicle, pickup truck, v vehicle can expose you to chemicals including engine exhaust, carbon monoxide, phtl lead, which are known to the State of California to cause cancer and birth defects or other reproductive harm. To minimize exposure, avoid breathing exhaust, do not idle the engine except as necessary, service your vehicle in a well-ventilated area and wear gloves or wash your hands frequently when servicing your vehicle. For more information go to [www.P65Warnings.ca.gov/passenger-vehicle](http://www.P65Warnings.ca.gov/passenger-vehicle).

rates may apply. Text HELP for help



[www.ford.com/help/privacy-terms/](http://www.ford.com/help/privacy-terms/)