



ford.com

VEHICLE DESCRIPTION

SUPER DUTY

2025 F350 SRW 4X4 REG CAB XL 142" WB STYLESIDE 6.8L DEVCT NA PFI V8 ENGINE 10-SPEED AUTO TORQSHIFT-G

EXTERIOR

OXFORD WHITE

INTERIOR

MEDIUM DARK SLATE CLOTH

SE

D99086

STANDARD EQUIPMENT INCLUDED AT NO EXTRA CHARGE

EXTERIOR

- DOOR HANDLES - BLACK
- HEADLAMPS - AUTOLAMP (ON/OFF)
- TOW HOOKS
- TRAILER SWAY CONTROL
- TRAILER TOW MIRRORS
- WIPERS- INTERMITTENT

INTERIOR

- 4.2" PRODUCTIVITY SCREEN
- AIR COND, MANUAL FRONT
- CLOTH SUN VISORS
- DRIVER SEAT-MANUAL LUMBAR
- OUTSIDE TEMP DISPLAY
- PARTICULATE AIR FILTER
- POWER LOCKS AND WINDOWS
- STEERING:TILT/TELESCOPE, CRUISE & AUDIO CONTROLS

FUNCTIONAL

- 4-WHEEL ANTILOCK BRAKE SYS
- FORDPASS™ CONNECT 5GWI-FI HOTSPOT TELEMATICS MODEM
- HILL START ASSIST
- MANUAL LOCKING HUBS
- MONO BEAM COIL SPRING FRT SUSPENSION W/STAB BAR
- REAR VIEW CAMERA
- REMOTE KEYLESS ENTRY
- SYNC®4 W/8" SCREEN

SAFETY/SECURITY

- ADVANCETRAC™ WITH RSC®
- AIRBAGS - SAFETY CANOPY®
- BELT-MINDER CHIME
- DRIVER/PASSENGER AIR BAGS
- SECURE PKG 1 YR INCLUDED
- SECURILOCK® ANTI-THEFT SYS
- SOS POST-CRASH ALERT SYS™

WARRANTY

- 3YR/36,000 BUMPER / BUMPER
- 5YR/60,000 POWERTRAIN
- 5YR/60,000 ROADSIDE ASSIST
- 5YR/100,000 DIESEL ENGINE

INCLUDED ON THIS VEHICLE

OPTIONAL EQUIPMENT/OTHER

PREFERRED EQUIPMENT PKG.610A 10-SPEED AUTO TORQSHIFT-G 3.73 RATIO NON LTD SLIP AXLE FRONT LICENSE PLATE BRACKET STX APPEARANCE PACKAGE .LT275/70R18E BSW ALL TERRAIN .BLIS (BLIND SPOT INFO SYSTEM) .EBONY BLACK ALUM WHLS-18" .LED BOX LIGHTING .REAR PARKING SENSORS .360-DEGREE CAMERA PACKAGE .CLOTH 40/20/40 SEAT 11400# GVWR PACKAGE 50 STATE EMISSIONS SNOW PLOW PREP PACKAGE TRAILER BRAKE CONTROLLER JACK UPFITTER SWITCHES 410 AMP DUAL ALTERNATOR DUAL BATTERY XL DRIVER ASSIST PACKAGE

(MSRP)

NO CHARGE

NO CHARGE

NO CHARGE

5,115.00

NO CHARGE

250.00

300.00

230.00

115.00

210.00

NO CHARGE

PRICE INFORMATION

BASE PRICE

\$49,395.00

TOTAL OPTIONS/OTHER

6,220.00

TOTAL VEHICLE & OPTIONS/OTHER

55,615.00

DESTINATION & DELIVERY

2,095.00

TOTAL BEFORE DISCOUNTS

57,710.00

STX APPEARANCE PKG

- 1,000.00

TOTAL SAVINGS

- 1,000.00

(MSRP)

	RAMP ONE		TOTAL MSRP \$56,710.00
	RW73	RAIL	
	RAMP TWO	ITEM #:	Scan The QR Code to get more details about this vehicle
		41-3028 O/T 2	
	This label is affixed pursuant to the Federal Automobile Information Disclosure Act. Gasoline, License, and Title Fees, State and Local taxes are not included. Dealer installed options or accessories are not included unless listed above.		SF021 N RB 2X 530 001824 06 02 25

California Air Resources Board

Gasoline Vehicle

Environmental Performance

These ratings are not directly comparable to the U.S. EPA/DOT light-duty vehicle label ratings. For information on how to compare, please see [www.arb.ca.gov/ep\\_label](http://www.arb.ca.gov/ep_label).

Protect the environment. Choose vehicles with higher ratings:

Greenhouse Gas Rating (tailpipe only)

A+

Cleaner

Smog Rating (tailpipe only)

A+

Cleaner

Vehicle emissions are a primary contributor to climate change and smog. Ratings are determined by the California Air Resources Board based on this vehicle's measured emissions.



48 YEARS BUILT Ford TOUGH

F-SERIES®

AMERICA'S BEST SELLING TRUCKS

The FordPass™ Connect modem is active and sending vehicle data (e.g., diagnostics) to Ford.\*\* See in-vehicle settings for connectivity options.

\*Based on 1977–2024 CY total sales.

\*\*FordPass Connect (optional on select vehicles), the FordPass App and complimentary Connected Service are required for remote features (see FordPass Terms for details). Connected service and features depend on compatible AT&T network availability. Evolving technology/cellular networks/vehicle capability may limit functionality and prevent operation of connected features. Connected service excludes WI-FI hotspot.

1FTRF3BA7SED99086



 **WARNING:** Operating, servicing and maintaining a passenger vehicle, pickup truck, v vehicle can expose you to chemicals including engine exhaust, carbon monoxide, phtl lead, which are known to the State of California to cause cancer and birth defects or other reproductive harm. To minimize exposure, avoid breathing exhaust, do not idle the engine except as necessary, service your vehicle in a well-ventilated area and wear gloves or wash your hands frequently when servicing your vehicle. For more information go to [www.P65Warnings.ca.gov/passenger-vehicle](http://www.P65Warnings.ca.gov/passenger-vehicle).

Credit

Get Prequalified now at [www.ford.com/finance](http://www.ford.com/finance)