FD

120230927 **7585**

ULC U W OK C CERT CERT CERT TRD RAMP BUMP CAMP BOOK EXFL ROTA

ford.com	DESCRIPTION -150 LIGH 2023 F-150 4X4 SUPERCRE 145" WHEELBASE DUAL EMOTOR-STANDARD SINGLE-SPEED TRANSMISS	W EX BATTRY INT	PW TERIOR CARBONIZED GRAY ME TERIOR DARK SLATE CLOTH 40		EPA DOT Fuel Economy an Fuel Economy Fuel Economy MP	
 DAYTIME RUNNING LAMPS HEADLAMPS - AUTO HIGH BEAM HEADLAMPS - AUTOLAMP (ON/OFF) LARGE FRONT TRUNK AREA LED PROJECTOR W/ DYNAMIC BENDING HEADLAMPS LED SIDE-MIRROR SPOTLIGHTS LOCKING REMOVABLE TAILGATE WITH TAILGATE ASSIST 	INTERIOR 12" PRODUCTIVITY SCREEN 1TOUCH UP/DOWN DR/PASS WIN 60/40 FOLD-UP REAR BENCH A/C W/DUAL CLIMATE CONTROL AUTO-DIM REARVIEW MIRROR HEATED CLOTH FRONT SEATS ILLUMINATED ENTRY INTERIOR WORK SURFACE MESSAGE CTR: OUTSIDE TEMP, COMPASS, TRIP COMPUTER POWER DRIV SEAT - 8-WAY POWERPOINT - 2 120V REAR-WINDOW DEFROSTER TILT/TELESCOPE STR COLUMN (MSRP) 500.00	EUNCTIONAL 9 360-DEGREE CAME 9 CLASS IV TRAILER 9 FORDPASS CONNE HOTSPOT TELEMAX 9 FORWARD SENSIN 1 LANE-KEEPING SY 9 POST-COLLISION AS 9 REVERSE BRAKE A 9 REVERSE SENSING REAR VIEW CAMEP 9 SECURICODE, KEY 9 SIRIUSXM® W/3600 9 YNC®4 W/EVR & 1000 100	ERA ADVA AFFIC ALERT AIRBA HITCH AG AIRBA TICS MODEM LED C IG SYSTEM STEM SSIST W/AEB SSIST W/AEB ASSIST 3YR/3 SAND 5YR/6 A SYR/6 A SYR/6	6,000 BUMPER / BUMPER 0,000 POWERTRAIN 0,000 ROADSIDE ASSIST 0,000 SAFETY RAINT SYS 00,000 ELECTRIC LE COMPONENTS (MSRP) \$54,995.00 500.00 NS/OTHER 55,495.00	Charge Time: 11.9 hours(240V)Annual fuelCOST\$1,0501This veh	highw 160 200 Economy Economy Economy from gener ng driving co PG and costs dge and smog e vehicles SAFET Not Ra and rollover. similar size a Not Ra Not Ra
	RAMP ONE CA28 RAMP TWO	CONVOY ^{M#:} 52-7101 O/T 2	- Find vehicle, you'	u decide to lease or finance your Il find the choices that are right your dealer for details or visit	1FTVW1EL4PW	ntaining a pa
	This label is affixed pursuant to the Federal Automobile Information Disclosure Act. Gasoline, License, and Title Fees, State and Local taxes are not included. Dealer installed options or accessories are not included unless listed above. PJ143 R RB 2X 370 001164 09 14 2		0 001164 09 14 23	California to cause cancer and birth defects or other rep or wash your hands frequently when servicing your vehi For more information go to www.P65Warnings.ca.gov/p		

