
KAN-001301 99	74B 503 7B X X LABL ADJ COV PRCS	B10 RAMP BUMP	E1Y85RKB79707	TRANSIT	MAIL	12
Ford	1024 150 LR CARGO RWD	EXTERIO OXFO INTERIOF	R RD WHITE	9707	California Air Re	esources Boa
ford.com	3.5L PFDI V6 (GAS) 10-SPEED TRANSMISSION		, У СLОТН			<i>in onnie</i>
STANDARD EQUIPMENT INCLUDED	AT NO EXTRA CHARGE				These ratings are no For inform	ot directly comparal ation on how to co
EXTERIOR • AUXILIARY FUEL PORT • BODY SIDE MOLDINGS - BLACK • BUMPERS - CARBON BLACK • FULL SIZE SPARE TIRE/WHEEL • HEADLAMP COURTESY DELAY • WIPERS - RAIN-SENSING	INTERIOR • AIR CONDITIONING • ASSIST HANDLE - B-PILLAR • ASSIST HANDLES - A-PILLAR • CENTER CONSOLE • INTERIOR LIGHTING - LED • LOCKING GLOVE BOX • POWERPOINT - 12V (FRONT) • STEERING - TILT/TELESCOPIC • TACHOMETER	FUNCTIONAL • AUTO HIGH-BEAM HEADL • ELECTRONIC PWR ASST S • FORWARD COLLISION WA • HILL START ASSIST • LANE-KEEPING SYSTEM • POST-COLLISION BRAKIN • PRE-COLLISION ASSIST W • REAR VIEW CAMERA W/ TRAILER HITCH ASSIST • SELECTABLE DRIVE MOD	STEER • ADVANCETRACT IRNING • AIRBAGS ⊠ FROM SAFETY CANOPY • BRAKES - 4WHE G • SECURILOCK® A I//AEB • SOS POST-CRAST • TIRE PRESSURE • TIRE PRESSURE	[™] BELTS [™] WITH RSC® NT, SIDE AND (® SYSTEM EL DISC W/ABS ANTI-THEFT SYS SH ALERT SYS™		environment.
		• SIDE-WIND STABILIZATIO	N • 3YR/36,000 BUM • 5YR/60,000 POW • 5YR/60,000 ROA	/ERTRAIN	Cleaner	Using alterna
INCLUDED ON THIS VEHICLE	(MSRP)			(MSRP)	Vehicle emissions are a pri California Air Resources Bo	
PREFERRED EQUIPMENT PKG.101A 3.73 NON-LIMITED SLIP AXLE FRONT LICENSE PLATE BRACKET 180 DEGREE OPENING 8800# GVWR PACKAGE 2WAY D/P NO ARM REST EB CLTH 50 STATE EMISSIONS REVERSE SENSING SYSTEM HALOGEN HEADLAMPS E-85 FLEX FUEL CAPABLE	NO CHARGE NO CHARGE NO CHARGE NO CHARGE NO CHARGE 295.00 - 455.00 NO CHARGE		SE PRICE TAL OPTIONS/OTHER TAL VEHICLE & OPTIONS/OTHER STINATION & DELIVERY	\$47,165.00 - 160.00 - 47,005.00 2,095.00		
					FrontalDriverCrashPasseBased on the risk of injury in a f Should ONLY be compared to cSideFrontCrashRear	enger \star frontal impact. other vehicles of similar si seat Not
					Based on the risk of injury in a s Rollover Based on the risk of rollover in a	Not
					Star ratings range from 1 to Source: National Highw www.saf	
	RAMP ONE CL42		OTAL MSRP \$4	9,100.00		FTYE1Y85RKB79707
	RAMP TWO	74-C803 O/T 2 For	vehicle, you'll find the c d Credit for you. See your dealer www.ford.com/finance	e choices that are right ler for details or visit	WARNING: Operating, ser vehicle can expose you to lead, which are known to the Stat	chemicals including engine te of California to cause ca
	This label is affixed pursuant to the Federal Automobile Information Disclosure Act. Gasoline, License, and Title Fees, State and Local taxes are not included. Dealer installed options or accessories are not included unless listed above.		B865 A 7BX X 450 001301 04 03 25		To minimize exposure, avoid breat vehicle in a well-ventilated area a For more information go to www.	athing exhaust, do not idle



ated

vith 5 being the highest. nistration (NHTSA). 4236



assenger vehicle, pickup truck, v e exhaust, carbon monoxide, phtl heer and birth defects or other reproductive narm. he engine except as necessary, service your ur hands frequently when servicing your vehicle. nger-vehicle.

rates may apply. Text HELP for help

The FordPass Connect™ modem is active and sending vehicle data (e.g., diagnostics) to Ford. See

in-vehicle Settings for connectivity options.



www.ford.com/help/privacy-terms/