U | R | FL | UTC CERT CERT CERT TRD RAMP BUMP CAMP BOOK EXFL ROTA

Go Further ford.com	GE 2022 EDGE SEL AWD 5-PASSENGER TWIN-SCRL 2.0L ECOBOOST ENG 3-SPD AUTO TRANSMISSION		NB B03657 e ex seat material	EPA DOT Fuel Economy and En Fuel Economy P 22 MPG Small SU The best
BELTLINE MOLDING- BRIGHT     ITT     DOOR HANDLES - BODY COLOR     EASY FUEL® CAPLESS FILLER     AL     HEADLAMPS - AUTO HIGH BEAM     CL     HEADLAMPS - WIPER ACTIVATED     DL     HEADLAMPS - LED WITH     DL     SIGN LTG W/DARK BEZEL     AU     MIRRORS-HTD/POWER GLASS,     LE     MANUAL FOLD     W/     PRIVACY GLASS - REAR DOORS     REAR INT WIPER/WASH/DFRST     TAILLAMPS-LED     INCLUDED ON THIS VEHICLE     EQUIPMENT GROUP 201A     OPTIONAL EQUIPMENT/OTHER     .18" SPLT-SPK SLVR PTD ALUM WH 245/60R18 A/S BSW TIRES	TRA CHARGE ERIOR OUCH UP/DOWN DR/PASS WIN /40 EASYFOLD REAR BENCH UTO-DIM REARVIEW MIRROR UTO-DIM REARVIEW HARGE 100.00 45.00	<ul> <li>EUNCTIONAL</li> <li>AWFM/MP3, 6 SPEAKERS</li> <li>AUTO START STOP TECH</li> <li>ELECTRONIC PWR ASST STEER</li> <li>FORDPASS™ CONNECT 4GWI-FI HOTSPOT TELEMATICS MODEM</li> <li>INTELL ACCESS W/PUSH START</li> <li>REAR VIEW CAMERA W/WASHER</li> <li>SIRIUSXM® W/360L- NA AK&amp;HI</li> <li>SYNC®4A W/EVR &amp; 12" SCREEN</li> </ul>	\$39,210.00 NS/OTHER 145.00 LE & OPTIONS/OTHER 39,355.00	Image: Addition of the second state
	RAMP ONE RS14 RAMP TWO ITEM #: 71 This label is affixed pursuant to the Information Disclosure Act. Gasolin State and Local taxes are not includ options or accessories are not includ	I-3468 O/T 4C Federal Automobile ne, License, and Title Fees, led. Dealer installed	MSRP \$40,850.00 Whether you decide to lease or finance your rehicle, you'll find the choices that are right or you. See your dealer for details or visit vww.ford.com/finance. PECIAL ORDER BB 2XX 240 000244 10 28 22	Star ratings range from 1 to 5 stars (****), Source: National Highway Traffic Safety Adm www.safercar.gov or 1-888-327 2FMPK4J99NBB03657 WARNING: Operating, servicing and maintaining a p vehicle can expose you to chemicals including engin- lead, which are known to the State of California to cause ca To minimize exposure, avoid breathing exhaust, do not idle vehicle in a well-ventilated area and wear gloves or wash yo For more information go to www.P65Warnings.ca.gov/passe

