STANDARD EQUIPMENT INCLUDED A EXTERIOR • BLACK FORD OVALS • DOOR HANDLES - BODY COLOR • EASY FUEL® CAPLESS FILLER • ENCLOSED BED STORAGE • FLEXBED™ STORAGE SYSTEM • FOG LAMPS • GRILLE - BLACK • HEADLAMPS- LED WITH SIGNATURE LIGHTING • PAINTED REAR BUMPER • PAINTED REAR BUMPER • PAINTED ROCKERS • POWER MIRRORS • POWER TAILGATE LOCK • ROOF PAINTED BLACK • UNIQUE FRONT FASCIA	INTERIOR • 1-TOUCH DOWN DRIVER WINDO • 2ND ROW BENCH FLIP-UP W/ UNDER-SEAT STORAGE • 8.0" PRODUCTIVITY SCREEN • ACTIVEX TRIMMED SEATS • BLUE AND LIME ACCENTS • CRUISE CONTROL • MANUAL A/C, SINGLE ZONE • PADDLE SHIFTERS • PARTICULATE AIR FILTER • POWER LOCKS AND WINDOWS	ELECTRIC PARKING     FORDPASS™ CONN HOTSPOT TELEMATI     INTELL ACCESS W/F     LOBO DRIVE MODE     LOWERED RIDE HEIG     PRE-COLLISION ASS	BRAKE • BELT-MIN ECT 5GWI-FI • LATCH CH CS MODEM • PERIMETI • SECURILO • TIRE PRE	- SAFETY CANOPY® IDER CHIME HILD SAFETY SYSTEM	combined city/hwy 21 30 highway 4.2 gallons per 100 miles
INCLUDED ON THIS VEHICLE EQUIPMENT GROUP 402A OPTIONAL EQUIPMENT/OTHER 50 STATE EMISSIONS 19X7.5 ALLOY WHEEL STYLE A	POWERPOINTS - 12V     ROTARY GEAR SHIFT DIAL     VINYL SOFT CONSOLE LID      (MSRP)      NO CHARGE	REAR VIEW CAMERA SELECTABLE DRIVE SYNC®4 W/EVR & 13 TUNED SUSPENSION TWIN CLUTCH REAR TWIN CLUTCH REAR OFFICE	WARRANT         • 3YR/36,00           MODES         • 5YR/60,00           8.2" SCRN         • 5YR/60,00           • 8YR/100,00         • 8YR/100,00	SSURE MONIT SYS  Y 00 BUMPER / BUMPER 00 POWERTRAIN 00 ROADSIDE ASSIST 000 HYBRID UNIQUE IENTS IF EQUIPPED  (MSRP) \$35,930.00	Annual fuel Cost   \$2,2,2000   \$2,2,2000   The series of the se
		RAIL ITEM #: 71-590U O/T 2 uant to the Federal Automobile	TOTAL MSRP         Ford Credit         Whether you develoce, you'll fir for you. See you www.ford.com/	\$37,625.00 cide to lease or finance your nd the choices that are right r dealer for details or visit finance.	<b>SFTCW8TA9SRA8323</b> <b>WARNING:</b> Operating, servicing and maintaining a vehicle can expose you to chemicals including engi lead, which are known to the State of California to cause c To minimize exposure, avoid breathing exhaust, do not idle

