| HRM-006392 <sub>VA</sub>  | 9-NORMAL,NB,106392,SD091 <b>4</b>   | 338   | UTC     U     W     VA       CERT     CERT     CERT     TRD     RAMP     BUMP   | CAMP BOOK EXFL ROTA 3582  |
|---|---|---|---|---|
| ford.com  | EHICLE DESCRIPTION<br>MAVERICK<br>2025 XL FWD<br>121" WHEELBASE<br>2.5L HYBRID ENGINE<br>POWER-SPLIT ELECTRIC CN<br>D AT NO EXTRA CHARGE  | EXTERIOR<br>OXFORD WHI<br>INTERIOR<br>/T BLACK ONYX   | SR A72398<br>TE<br>A-MED DK SLATE TRI   | Fuel Economy and Environment<br>Fuel Economy<br>MPG. The b<br>MPG. The b  |
| EXTERIOR<br>• CARGO BOX TIE DOWN HOOKS<br>• DAYTIME RUNNING LAMPS<br>• DOOR HANDLES - BLACK<br>• EASY FUEL® CAPLESS FILLER<br>• FLEXBED™ STORAGE SYSTEM<br>• GRILLE - BLACK MESH<br>• HEADLAMPS-LED AUTO HI-BEAM<br>• HEADLAMPS-LED AUTO ON/OFF<br>• LED REFLECTOR HEADLAMPS<br>• MANUAL LOCKING TAILGATE<br>• WIPERS- INTERMITTENT | INTERIOR<br>• 1-TOUCH DOWN DRIVER WINDOW<br>• 2ND ROW BENCH FLIP-UP W/<br>UNDER-SEAT STORAGE<br>• 8.0" PRODUCTIVITY SCREEN<br>• CLOTH BENCH REAR SEAT<br>• CRUISE CONTROL<br>• DUAL USB<br>• MANUAL A/C, SINGLE ZONE<br>• POWER LOCKS AND WINDOWS<br>• POWERPOINTS - 12V<br>• ROTARY GEAR SHIFT DIAL<br>• TILT/TELESCOPE STR COLUMN<br>• VINYL SOFT CONSOLE LID | <ul> <li>EUNCTIONAL</li> <li>4-WHEEL ANTILOCK BRAKE SYS</li> <li>BATTERY SAVER FEATURE</li> <li>ELECTRIC PARKING BRAKE</li> <li>ELECTRONIC PWR ASST STEER</li> <li>FORDPASS™ CONNECT 5GWI-FI<br/>HOTSPOT TELEMATICS MODEM</li> <li>PRE-COLLISION ASSIST W/AEB</li> <li>REAR VIEW CAMERA</li> <li>REMOTE KEYLESS ENTRY</li> <li>SELECTABLE DRIVE MODES</li> <li>SYNC®4 W/EVR &amp; 13.2" SCRN</li> </ul> | SAFETY/SECURITY<br>• AIRBAGS - SAFETY CANOPY®<br>• BELT-MINDER CHIME<br>• LATCH CHILD SAFETY SYSTEM<br>• SECURILOCK® ANTI-THEFT SYS<br>• TIRE PRESSURE MONIT SYS<br>• TIRE PRESSURE MONIT SYS<br>• MAREANTY<br>• 3YR/36,000 BUMPER / BUMPER<br>• 5YR/60,000 POWERTRAIN<br>• 5YR/60,000 POWERTRAIN<br>• 5YR/60,000 ROADSIDE ASSIST<br>• 8YR/100,000 HYBRID UNIQUE<br>-COMPONENTS IF EQUIPPED | combined city/hwy city highway<br>2.6 gallons per 100 miles<br>Annual fuel COST<br>\$1,4000<br>This vehicle emits 234<br>distributing fuel also created   |
| INCLUDED ON THIS VEHICLE<br>EQUIPMENT GROUP 100A<br>OPTIONAL EQUIPMENT/OTHER<br>50 STATE EMISSIONS<br>FRONT LICENSE PLATE BRACKET   |   |   | \$26,995.00   | Actual results will vary for many reasons, including driving convehicle. The average new vehicle gets 28 MPG and costs \$9,50 based on 15,000 miles per year at \$3,50 per gallon. MPGe is memissions are a significant cause of climate change and smog.<br><b>fueleconogy</b><br>Calculate personalized estimates and compare vehicles<br><b>GOVERNMENT 5-STAR SAFETY</b><br><b>Overall Vehicle Score</b><br>Based on the combined ratings of frontal, side and rollover.<br>Should ONLY be compared to other vehicles of similar size a<br><b>Frontal</b><br>Driver<br><b>Crash</b><br>Based on the risk of injury in a frontal impact.<br>Should ONLY be compared to other vehicles of similar size a<br><b>Side</b><br><b>Crash</b><br>Based on the risk of injury in a side impact.<br>Should ONLY be compared to other vehicles of similar size a<br><b>Side</b><br><b>Crash</b><br>Based on the risk of injury in a side impact.<br>Based on the risk of injury in a side impact.<br><b>Star ratings range from 1 to 5 stars (</b> * * * * *), with<br>Source: National Highway Traffic Safety Administ<br>www.safercar.gov or 1-888-327-42 |
|   | CA2L  | ΤΟΤΑΙ   | . MSRP \$28,590.00  | 3FTTW8A39SRA72398   |
|   | RAMP TWO         ITEN           This label is affixed pursuant<br>Information Disclosure Act.<br>State and Local taxes are not<br>options or accessories are monoptions   | 27-F83W O/T 2 Ford Credit<br>to the Federal Automobile<br>Gasoline, License, and Title Fees,<br>tincluded. Dealer installed SD091 N   | Whether you decide to lease or finance your<br>vehicle, you'll find the choices that are right<br>for you. See your dealer for details or visit<br>www.ford.com/finance.<br>RB 2X 550 006392 04 09 25   | WARNING: Operating, servicing and maintaining a pass<br>vehicle can expose you to chemicals including engine e<br>lead, which are known to the State of California to cause cance<br>To minimize exposure, avoid breathing exhaust, do not idle the<br>vehicle in a well-ventilated area and wear gloves or wash your<br>For more information go to www.P65Warnings.ca.gov/passeng  |

