HRM-008072 _{PA}	9-NORMAL,NB,108072,SF051 74	07		W PA Ampbumpcam	PBOOKEXFLROTABATT	00 5012,
	HICLE DESCRIPTION MAVERICK 2025 XL AWD 121" WHEELBASE 2.0L ECOBOOST ENGINE AUTOMATIC TRANSMISSION	EXTERIOR OXFORD W INTERIOR BLACK ON ELACK ON ELACK ON ELACK ON ELACK ON ELECTRONIC PWR ASST STEEF FORDPASS™ CONNECT 5GWI-F HOTSPOT TELEMATICS MODEM PRE-COLLISION ASSIST W/AEB PRE-COLLISION ASSIST W/AEB PRE-COLLISION ASSIST W/AEB REMOTE KEYLESS ENTRY SELECTABLE DRIVE MODES SYNC®4 W/EVR & 13.2" SCRN PRICE IN BASE PR TOTAL O	OXFORD WHITE ITERIOR BLACK ONYX-MED DK SLATE TRI SAFETY/SECURITY OK BRAKE SYS FEATURE NG BRAKE NAEST STEER NNECT 5GWI-FI ATICS MODEM ASSIST W/AEB ERA S ENTRY VE MODES		Fuel Economy Fuel Economy MPG Mail Pickup MPG Mail Pic	
					CrashPassengBased on the risk of injury in a frontShould ONLY be compared to otherSideFront seaCrashRear seaBased on the risk of injury in a sideRolloverBased on the risk of rollover in a sinStar ratings range from 1 to 5 siSource: National Highway Twww.saferca	al impact. r vehicles of similar size a at $\star \star$ impact. mgle-vehicle crash. tars ($\star \star \star \star$), with
	CU2G	тот	AL MSRP \$31,5	505.00	3FTT	W8BA5SRA96016
	RAMP TWO	get m	The QR Code to ore details about rehicle		WARNING: Operating, servicin vehicle can expose you to cher lead, which are known to the State of	ig and maintaining a pass micals including engine e: California to cause cance
	This label is affixed pursuant to Information Disclosure Act. Gas State and Local taxes are not inc options or accessories are not i	coline, License, and Title Fees, cluded. Dealer installed SF051	N RB 2X 560 008072 06 ()5 25	To minimize exposure, avoid breathing vehicle in a well-ventilated area and w For more information go to www.P65V	g exhaust, do not idle the vear gloves or wash your h Narnings.ca.gov/passeng

