HRM-002983 GA	9-NORMAL, NB, 202983, SA242 36	504	UTCUWGACERTCERTTRDRAMPBUMP	CAMPBOOKEXFLROTA 00 945/
	HICLE DESCRIPTION MARGENER MARGENE	<section-header>EXTERIOR SPACE WHITE INTERIOR BLACK ONYX</section-header>	CERT CERT CERT TRD RAMP BUMP SR A27207 METALLIC METALLIC MED DK SLATE TRI SAFETY/SECURITY AIRBAGS - SAFETY CANOPY® BELT-MINDER CHIME AIRBAGS - SAFETY SYSTEM BELT-MINDER CHIME AIRBAGS - SAFETY SYSTEM AIRBAGS - SAFETY SYSTEM AIRBAGS - SAFETY CANOPY® BELT-MINDER CHIME AIRBAGS - SAFETY SYSTEM AIRBAGS - SAFETY CANOPY® AIRBAGS - SAFETY CANOPY®	AMP BOOK EXFL ROTA 945 CAMP BOOK EXFL ROTA 945 COMP BOOK EXFL ROTA 1 1 1 1 1 1 1 1 1 1 1 1 1
		IGG		Should ONLY be compared to other vehicles of similar size and Frontal Driver * * * Crash Passenger * * * Based on the risk of injury in a frontal impact. Should ONLY be compared to other vehicles of similar size and Side Front seat * * * Crash Rear seat * * * Based on the risk of injury in a side impact. Based on the risk of injury in a side impact. Rollover * * * Based on the risk of rollover in a single-vehicle crash. Star ratings range from 1 to 5 stars (* * * * *), with Source: National Highway Traffic Safety Administ www.safercar.gov or 1-888-327-42
	CH02	TOTAL		3FTTW8BA8SRA27207
	This label is affixed pursuant to	# 21-104X O/T 2 Ford Credit	Whether you decide to lease or finance your vehicle, you'll find the choices that are right for you. See your dealer for details or visit www.ford.com/finance.	WARNING: Operating, servicing and maintaining a pass vehicle can expose you to chemicals including engine ex lead, which are known to the State of California to cause cancer
		asoline, License, and Title Fees, ncluded. Dealer installed SA242 N I	RB 2X 540 002983 01 24 25	To minimize exposure, avoid breathing exhaust, do not idle the ovehicle in a well-ventilated area and wear gloves or wash your h For more information go to www.P65Warnings.ca.gov/passenge

