HRM-005481 _{PA}	9-NORMAL,NB,105481,SE231 455	5	UTC U W PA CERTCERTCERT TRD RAMPBUMPCAM	PBOOKEXFLROTABATT 3428
	ICLE DESCRIPTION MAVERICK 2025 XLT FWD 121" WHEELBASE 2.5L HYBRID ENGINE POWER-SPLIT ELECTRIC CVT	EXTERIOR SHADOW BL INTERIOR NAVY PIER -	SR B07206 ack med slate trim	EPA DOT Fuel Economy and En Fuel Economy MPG. The b
STANDARD EQUIPMENT INCLUDED A EXTERIOR • CARGO BOX TIE DOWN HOOKS • DAYTIME RUNNING LAMPS • DOOR HANDLES - BLACK • EASY FUEL® CAPLESS FILLER • ENCLOSED BED STORAGE • FLEXBED [™] STORAGE SYSTEM • HEADLAMPS -WIPER ACTIVATED • HEADLAMPS -LED AUTO ON/OFF • LED REFLECTOR HEADLAMPS • POWER MIRRORS • POWER TAILGATE LOCK • TRAILER TOW HITCH • WIPERS- INTERMITTENT INCLUDED ON THIS VEHICLE EQUIPMENT GROUP 300A OPTIONAL EQUIPMENT/OTHER 50 STATE EMISSIONS FORD CO-PILOT360® 1.0 .REAR PARKING SENSORS	INTERIOR • 1-TOUCH DOWN DRIVER WINDOW • 2ND ROW BENCH FLIP-UP W/ UNDER-SEAT STORAGE • 8.0" PRODUCTIVITY SCREEN • 8.0" PRODUCTIVITY SCREEN • CRUISE CONTROL • DUAL USB • MANUAL A/C, SINGLE ZONE • PARTICULATE AIR FILTER • POWER LOCKS AND WINDOWSS • POWERPOINTS - 12V • ROTARY GEAR SHIFT DIAL • UNIQUE CLOTH BUCKET SEATS • VINYL SOFT CONSOLE LID IMSRP	TOTAL VEH		Josop of signal sig
	RAMP ONE	τοται	L MSRP \$33,135.00	Based on the risk of rollover in a single-vehicle crash. Star ratings range from 1 to 5 stars (★★★★), w Source: National Highway Traffic Safety Admin www.safercar.gov or 1-888-327-4 3FTTW8H30SRB07206
			Whether you decide to lease or finance your vehicle, you'll find the choices that are right f for you. See your dealer for details or visit www.ford.com/finance.	WARNING: Operating, servicing and maintaining a pas vehicle can expose you to chemicals including engine e lead, which are known to the State of California to cause canc
	This label is affixed pursuant to the Information Disclosure Act. Gasol State and Local taxes are not inclu options or accessories are not inc	line, License, and Title Fees, Ided. Dealer installed SE231 N	RB 2X 560 005481 05 23 25	To minimize exposure, avoid breathing exhaust, do not idle the vehicle in a well-ventilated area and wear gloves or wash your For more information go to www.P65Warnings.ca.gov/passeng

