| HRM-007813 _{CA} | 9-NORMAL,NB,007813,SF101 200 | 943 | CERTCERTCERT TRD RAMPBUMPCA | MPBOOKEXFLROTABATT 3582 |
|--|--|---|--|--|
| | AT NO EXTRA CHARGE | EXTERIOR OXFORD W INTERIOR NAVY PIER | SR B11298 HITE -MED SLATE TRIM | EPA DOT Fuel Economy and Env Fuel Economy MPG. The b |
| EXTERIOR • CARGO BOX TIE DOWN HOOKS • DAYTIME RUNNING LAMPS • DOOR HANDLES - BLACK • EASY FUEL® CAPLESS FILLER • ENCLOSED BED STORAGE • FLEXBED™ STORAGE SYSTEM • HEADLAMPS - WIPER ACTIVATED • HEADLAMPS -LED AUTO ON/OFF • LED REFLECTOR HEADLAMPS • POWER MIRRORS • POWER TAILGATE LOCK • TRAILER TOW HITCH • WIPERS- INTERMITTENT | INTERIOR • 1-TOUCH DOWN DRIVER WINDOW • 2ND ROW BENCH FLIP-UP W/ UNDER-SEAT STORAGE • 8.0" PRODUCTIVITY SCREEN • CRUISE CONTROL • DUAL USB • MANUAL A/C, SINGLE ZONE • PARTICULATE AIR FILTER • POWER LOCKS AND WINDOWS • POWERPOINTS - 12V • ROTARY GEAR SHIFT DIAL • UNIQUE CLOTH BUCKET SEATS • VINYL SOFT CONSOLE LID | EUNCTIONAL • BATTERY SAVER FEATURE • ELECTRIC PARKING BRAKE • ELECTRONIC PWR ASST STEER • FORDPASS™ CONNECT 5GWI-F HOTSPOT TELEMATICS MODEM • INTELL ACCESS W/PUSH START • PRE-COLLISION ASSIST W/AEB • REAR VIEW CAMERA • SELECTABLE DRIVE MODES • SYNC®4 W/EVR & 13.2" SCRN | • PERIMETER ALARM • SECURILOCK® ANTI-THEFT SYS | indext provide the second state of the second state o |
| INCLUDED ON THIS VEHICLE EQUIPMENT GROUP 300A OPTIONAL EQUIPMENT/OTHER BEDLINER - SPRAY-IN 50 STATE EMISSIONS | | BASE PRICE TOTAL OF TOTAL VE | (MSRP CE \$30,645.00 VIIONS/OTHER 495.00 HICLE & OPTIONS/OTHER 31,140.00 ION & DELIVERY 1,695.00 | fueleconomy.gov Calculate personalized estimates and compare vehicles |
| | RAMP ONE RA84 RAMP TWO | RAIL Scan get m | AL MSRP \$32,835.00 The QR Code to ore details about ehicle | 3FTTW8H37SRB11298 |
| | This label is affixed pursuant to th Information Disclosure Act. Gaso State and Local taxes are not inclu options or accessories are not inc | e Federal Automobile line, License, and Title Fees, uded. Dealer installed SF101 | SPECIAL ORDER N RB 2X 560 007813 06 10 25 | To minimize exposure, avoid breathing exhaust, do not idle the vehicle in a well-ventilated area and wear gloves or wash your l For more information go to www.P65Warnings.ca.gov/passenge |

