HRM-014205 AL	9-NORMAL, NB, 014205, SF251 174	····	CERTCERTCERT TRD RAMPBUMPCAM	
	INTERIOR • 1TOUCH UP/DOWN FRT/RR WIN • 2ND ROW BENCH FLIP-UP W/ UNDER-SEAT STORAGE • 8.0" PRODUCTIVITY SCREEN • 8.0" PRODUCTIVITY SCREEN • MBIENT LIGHTING • DUAL USB - REAR • DUAL ZONE AUTO CLIMATE CTL • ILUMINATED SUN VISORS • OWERPOINTS - 12W • REAR SEAT CUPHOLDERS AND ARMREST • SOFT VINYL WRAPPED/HEATED STEER WHL W/MOUNTED CNTRL	<section-header>EXERPTING SUBJECT OF SUBJIC OF SUBJECT OF SUBJIC OF SUBJIC OF SUBJIC OF SUBJIC OF SUBJIC OF SUBJECT OF SUBJIC OF SUBJICO OF SUBJICO OF SUBJICO OF SUBJICO OF SUBJICO OF SUBJICO</section-header>	SAFETY/SECURITY • AIRBAGS - SAFETY CANOPY® • BELT-MINDER CHIME • LATCH CHILD SAFETY SYSTEM • PERIMETER ALARM • SECURILOCK® ANTI-THEFT SYS • TIRE PRESSURE MONIT SYS WARRANTY • 3YR/36,000 BUMPER / BUMPER • 5YR/60,000 POWERTRAIN • 5YR/60,000 ROADSIDE ASSIST • SYR/100,000 HYBRID UNIQUE • COMPONENTS IF EQUIPPED MATION \$38,440.00 NS/OTHER • & OPTIONS/OTHER	fueleconomy.gov Calculate personalized estimates and compare vehicles
				Based on the risk of rollover in a single-vehicle crash. Star ratings range from 1 to 5 stars (★★★★), with Source: National Highway Traffic Safety Adminis www.safercar.gov or 1-888-327-42
	RAMP ONE RA3H	TOTAL		3FTTW8S35SRB18985
	RAMP TWO		e QR Code to	WARNING: Operating, servicing and maintaining a passe vehicle can expose you to chemicals including engine exl lead, which are known to the State of California to cause cancer
	This label is affixed pursuant to th Information Disclosure Act. Gaso State and Local taxes are not inclu options or accessories are not inclu	line, License, and Title Fees, uded. Dealer installed SF251 N R	B 2X 560 014205 06 25 25	To minimize exposure, avoid breathing exhaust, do not idle the e vehicle in a well-ventilated area and wear gloves or wash your h For more information go to www.P65Warnings.ca.gov/passenge

