		214			
Ford.com	2025 LARIAT AWD 121" WHEELBASE 2.0L ECOBOOST ENGINE AUTOMATIC TRANSMISSION	RUBY INTERIOR	SR B06991 EXTERIOR RUBY RED METALLIC TINTED CC INTERIOR SMOKED TRUFFLE TRIM		EPA DOT Fuel Economy and Env Fuel Economy MPG. The b
STANDARD EQUIPMENT INCLUDED A EXTERIOR ACOUSTIC-LAMINATE WINDSHLD BOX LIGHTING-LED DOOR HANDLES - BODY COLOR EASY FUEL® CAPLESS FILLER ENCLOSED BED STORAGE FLEXBED™ STORAGE SYSTEM HEADLAMPS- LED WITH SIGNATURE LIGHTING HEADLAMPS-LED AUTO HI-BEAM POWER HEATED MIRRORS POWER SLIDING REAR WINDOW POWER TAILGATE LOCK TOUGH BED® SPRAY-IN LINER TRAILER TOW HITCH WIPERS- INTERMITTENT INCLUDED ON THIS VEHICLE EQUIPMENT GROUP 502A OPTIONAL EQUIPMENT/OTHER 2025 MODEL YEAR RUBY RED METALLIC TINTED CC POWER MOON ROOF S0 STATE EMISSIONS 19X7.5 ALLOY WHEEL STYLE A REAR PARKING SENSORS	AT NO EXTRA CHARGE INTERIOR 1 TOUCH UP/DOWN FRT/RR WIN 2 ND ROW BENCH FLIP-UP W/ UNDER-SEAT STORAGE 2 8.0° PRODUCTIVITY SCREEN 3 MBIENT LIGHTING DUAL ZONE AUTO CLIMATE CTL 1 LLUMINATED SUN VISORS POWERPOINTS - 12V REAR SEAT CUPHOLDERS AND ARMREST 3 OFT VINYL WRAPPED/HEATED STEER WHL W/MOUNTED CNTRL	BAS TOT. TOT.	ST2.0 • BLIS W/ CTA GWI-FI • LANE KEEPING SYST DDEM • LATCH CHILD SAFET START • PERIMETER ALARM /AEB • TIRE PRESSURE MON SIST • WARRANTY • SYR/60,000 BUMPER • SYR/60,000 ROADSID	EM 7 SYSTEM THEFT SYS IIT SYS 7 BUMPER RAIN E ASSIST UNIQUE	Image: Solution of the set of the
	RAMP ONE RA4F	т	DTAL MSRP \$39,8	70.00	3FTTW8SA8SRB06991
	RAMP TWO	e ge	an The QR Code to t more details about is vehicle		WARNING: Operating, servicing and maintaining a pass vehicle can expose you to chemicals including engine e lead, which are known to the State of California to cause cance
	This label is affixed pursuant to Information Disclosure Act. Ga State and Local taxes are not in options or accessories are not	o the Federal Automobile Isoline, License, and Title Fees, Included. Dealer installed	E291 N RB 2X 560 007030 05 2		lead, which are known to the State of California to cause cance To minimize exposure, avoid breathing exhaust, do not idle the vehicle in a well-ventilated area and wear gloves or wash your For more information go to www.P65Warnings.ca.gov/passeng

